

# Mounting instruction



## Aircell<sup>®</sup> 5

SMA plug right-angle crimp / Item no.: 7752

[www.ssb-electronic.com](http://www.ssb-electronic.com)

<p>Required tools:</p> <ul style="list-style-type: none"><li>1 x cutter knife</li><li>1 x scissors</li><li>1 x crimping tool</li><li>1 x crimp insert HEX .213" (5,41 mm)</li><li>1 x crimp insert HEX .068" (1,72 mm)</li><li>1 x soldering station + solder</li><li>1 x screwdriver</li></ul>	<p><b>1</b> </p> <p>Cut off cable tail right-angled. Slide the crimp sleeve over the end of the cable.</p>
<p><b>2</b> </p> <p>Remove 16 mm of the outer jacket with the knife. Bend the copper braid up at a right angle.</p>	<p><b>3</b> </p> <p>Score and remove 5 mm of the copper foil with a cutter knife.</p>
<p><b>4</b> </p> <p>Score and remove 3 mm of the foamed dielectric with a cutter knife.</p>	<p><b>5</b> </p> <p>Insert the prepared cable end into the connector housing as far as it will go. Caution: the copper foil must fit tightly against the insulator so that the cable end can be inserted into the connector housing.</p>
<p><b>6</b> </p> <p>Cut off the copper braid with the scissors and push the crimp sleeve forward. Solder the inner conductor to the center contact.</p>	<p><b>7</b> </p> <p>Crimp the crimp sleeve with the crimping pliers. This clamps the copper braid between the connector housing and the crimp sleeve. Then screw the cap on tightly.</p>